6074 Keystone Rd 320-983-2447
Milaca, MN 56353 Fax: 320-983-2151

**PROPERTY INFORMATION** 

Location: 44655 - 237th Lane

Aitkin

Tax ID: 11-1-113300

Use: Residential, Single Family (3 bdrm)

System Design Flow: 200

GENERAL SYSTEM TYPE: ECO POD Res. 2x Yr. w/Test

Mail To: Kelly Mayo

9163 Woodland Drive Minnetrista, MN

55375

Fold Here

## **ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT**

Inspected: 04/29/2024 - Inspection Type: ROUTINE - Correction Status: No corrections made

Company: Work Performed By: Submitted 04/30/2024 by:

Septic Check Kyle Wade Heather Johnson

## **COMMENTS & GENERAL INSPECTION NOTES**

## Deficiencies Noted: deficiencies must be corrected to ensure proper longevity of the Onsite Sewage System.

The uv light was disconnected within the panel when I arrived. I connected the fuse to test it and the uv works fine. After speaking with Kelly, we decided to leave the uv off for the time being and see if the sample that I took today passes. If it does not pass we will need to come back and get it running and resample.

Everything else is in good working order.

#### **GENERAL SITE & SYSTEM CONDITIONS**

The General Site and System Conditions were:	Fully Inspected
Components accessible for service:	YES
All required service performed (if no - specify omitted inspection items in notes):	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO

## ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 1 Compartment - 600 Gallon Trash Tank		
Manufacturer: Local Manufacturer		
This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	
Aerobic Treatment Unit: ATU - Delta Ecopod, Manufacturer= Delta Environmental Products, Inc ECOPOD-E50 - 1,000 Gal Eco Pod E50		

Manufacturer: Delta Environmental Products, Inc. Model: ECOPOD-E50			
This component was:	Fully Inspected		
Effluent level within operational limits (if NO explain in comments):	YES		
Dissolved Oxygen within normal operating range (1.5 to 3.0 mg/L) (if less than 1.5 check blower and	N/A		
re-check):			
Field sample performance results within operational limits (Enter N/A if not performed):	N/A		
Trash Compartment solids accumulation within operational limits per manufacturer:	YES		
Clarifying Chamber solids accumulation within manufacturer operational limits:	YES		
Digester settleable solids test resulted in greater than 25% settleable solids: (If Yes, pumping needed):	NO		
Intake vent at blower housing and exhaust vent at digester clear of obstructions and operating	YES		
Applicable filters cleaned	YES		
Pumping needed:	NO		

Disinfection: Ultra Violet,	Manufacturer= Salcor Engineering - 3G

ReportID: 1283453

Manufacturer: Salcor Engineering Model: 3G		
This component was:	Fully Inspected	
Alarm mechanism functioning as intended:	YES	
Disinfection unit light on:	NO	Deficient

Fold

TANK: Pump Tank - 1,650 Gallon Pump Tank	
Manufacturer: Local Manufacturer	
This component was:	Fully Inspected
Compartment 1 Scum accumulation (Inches, if other specify):	0
Compartment 1 Sludge accumulation (Inches, if other specify):	0
Pumping recommended:	NO
Panel: Control - 1 Pump - Drainfield Dose Panel	
This component was:	Fully Inspected
Panel functioning (including alarm):	YES
Pump 1: on minutes (override in parentheses - if present):	2.5 min
Pump 1: off hours (override in parentheses - if present):	4
Pump 1: gallons per dose (override in parentheses - if present):	-
Pump 1: ETM hours (override in parentheses - if present):	68.39
Pump 1: Cycle Count (override in parentheses - if present):	2433
Pump: Effluent Pump - Drainfield Dose Pump	
This component was:	Fully Inspected
Controls functioning:	YES
Tested gallons per minute flow:	41.9
Media Filter: Mound - 10' x 38' Mound Rockbed	
Manufacturer: Site Constructed	
This component was:	Fully Inspected
Slope integrity maintained:	YES
Lateral lines flushed:	NO
Ponding present? If YES explain in comments:	NO
Average squirt height (if performed) (feet, if other specify):	-

# **SAMPLING REPORT**

Location: 44655 - 237th Lane

Aitkin

11-1-113300

Owner: Kelly Mayo
Use: Single Family

Service Company:

**Septic Check** 

6074 Keystone Rd Milaca, MN 56353 320-983-2447

Laboratory: A W Labs

Sample Date: 04/29/2024 Sample entered by: Heather Johnson Report submitted: 05/10/2024

Notes:

### **ONSITE SEWAGE SYSTEM SAMPLING DETAIL**

COMPONENT	TYPE	SAMPLE	LIMIT	RESULT	
Control - 1 Pump - Drainfield Dose Panel	Effluent	Flow	200 GPD	24.1	
Pump Tank - 1,650 Gallon Pump Tank	Effluent	Fecal	1,000 mg/L	7030	-Limit Exceeded