

Septic Check

6074 Keystone Rd
Milaca, MN 56353

320-983-2447
Fax: 320-983-2151

Mail To: Mille Lacs Corporate Ventures
700 Grand Avenue
Onamia, MN
56359

PROPERTY INFORMATION

Location: 36040 Hwy 65
McGregor
Tax ID: 30-0-033300

Use: Commercial, Other
System Design Flow: 900
GENERAL SYSTEM TYPE: COMM STAND - 1 NO TEST

Fold
Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 08/13/2024 - Inspection Type: ROUTINE - Correction Status: No corrections needed

Company:
Septic Check

Work Performed By:
Kyle Wade

Submitted 08/15/2024 by:
Heather Johnson

Fold
Here

COMMENTS & GENERAL INSPECTION NOTES

No Deficiencies Noted

Everything is in good working order.
No pumping required at this time.

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
Components accessible for service:	YES
All required service performed (if no - specify omitted inspection items in notes):	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 1 Compartment 2500 - Gal Septic Tank 1 w/Filter

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment 2500 - Gal Septic Tank 2 W/FILTER

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	

TANK: Pump Tank 4000 - GAL PUMP TANK

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

Panel: Control - 2 Pumps Mound Demand Dose Control Panel		
This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	-	
Pump 1: off hours (override in parentheses - if present):	-	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	530.31	
Pump 1: Cycle Count (override in parentheses - if present):	1634	
Pump 2: on minutes (override in parentheses - if present):	-	
Pump 2: off hours (override in parentheses - if present):	-	
Pump 2: gallons per dose (override in parentheses - if present):	-	
Pump 2: ETM hours (override in parentheses - if present):	222.00	
Pump 2: Cycle Count (override in parentheses - if present):	1602	
Pump: Effluent Pump Mound dose pump 1		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Pump: Effluent Pump Mound dose pump 2		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Drainfield (disposal): Pressure 10' x 100' Rockbed mound 1		
This component was:	Fully Inspected	
Lateral lines flushed:	NO	
Average squirt height (if performed) (feet, if other specify):	-	
Ponding present? If YES explain in comments:	NO	
Drainfield (disposal): Pressure 10' x 100' Rockbed mound 2		
This component was:	Fully Inspected	
Lateral lines flushed:	NO	
Average squirt height (if performed) (feet, if other specify):	-	
Ponding present? If YES explain in comments:	NO	