

Septic Check

6074 Keystone Rd
Milaca, MN 56353

320-983-2447
Fax: 320-983-2151

Mail To: Frank Merry
51856 209th Place
McGregor, MN

PROPERTY INFORMATION

Location: 51856 209th Place
McGregor
Tax ID: 29-1-410000

Use: Residential, Single Family (2 bdrm)
System Design Flow: 300
GENERAL SYSTEM TYPE: PEAT2 Res 1 /yr NO TEST

Fold
Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 07/24/2024 - Inspection Type: ROUTINE - Correction Status: Corrections in progress

Company:
Septic Check

Work Performed By:
Kyle Wade

Submitted 07/26/2024 by:
Heather Johnson

Fold
Here

COMMENTS & GENERAL INSPECTION NOTES

Deficiencies Were Noted: Corrections are in progress.

The peat has about reaches the end of it's life . It has broken down and compacted. I would recommend replacing the peat in both filters as it is no longer treating the waste water as it should. We will need to reach out to the customer with a quote . Everything else is in good working order. No pumping required at this time.

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
Components accessible for service:	YES
All required service performed (if no - specify omitted inspection items in notes):	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Trash Tank		
This component was:	Fully Inspected	
All required baffles in place (N/A = No baffles required):	YES	
Effluent level within operational limits (if NO explain in comments):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	4	
Compartment 1 Sludge accumulation (Inches, if other specify):	8	
Pumping recommended:	NO	
TANK: Pump Tank Peat Filter Dose tank		
This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	
Pump: Effluent Pump Peat Filter Dose Pump		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	29.3	
Panel: Control - 1 Pump		
Manufacturer: SJE Rhombus		
This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	50 sec	
Pump 1: off hours (override in parentheses - if present):	2	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	212.48	
Pump 1: Cycle Count (override in parentheses - if present):	14838	

Media Filter: Peat Filter, Manufacturer= Bord na Mona - other 2 Peat filters go to drainfield dose tank

Manufacturer: Bord na Mona Model: other		
This component was:	Fully Inspected	
Floats set and functioning properly:	N/A	
Lateral lines flushed:	YES	
Pod bottom cleaned	NO	
Filter media at levels per manufacturer recommendations	NO	
Filter media condition per manufacturer recommendations	NO	In Progress
Average squirt height (if performed) (feet, if other specify):	-	
Ponding present? If YES explain in comments:	NO	
Wastewater distributed equally throughout pod as designed	YES	
Sampling results within limits:	N/A	

TANK: Pump Tank Drainfield Dose Tank

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

Pump: Effluent Pump Drainfield Dose Pump

This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	

Drainfield (disposal): Pressure Bed 10' x 25' Pressure bed

This component was:	Not Inspected	
Lateral lines flushed:	NO	
Average squirt height (if performed) (feet, if other specify):	-	
Ponding present? If YES explain in comments:	NO	

SAMPLING REPORT

Location: 51856 209th Place
McGregor
29-1-410000

Owner: Frank Merry
Use: Single Family

Service Company:

Septic Check
6074 Keystone Rd
Milaca, MN 56353
320-983-2447

Sample Date: 07/24/2024 Sample entered by: Heather Johnson Report submitted: 07/26/2024

Notes:

ONSITE SEWAGE SYSTEM SAMPLING DETAIL

COMPONENT	TYPE	SAMPLE	LIMIT	RESULT
Pump Tank Drainfield Dose Tank	Effluent	Flow	300 gpd	71.7

This report indicates certain characteristics of the sample taken at the time of visit. In no way is this report a guarantee of operation or future performance.