

Septic Check

6074 Keystone Rd
Milaca, MN 56353

320-983-2447
Fax: 320-983-2151

Mail To: Richard Vigstol
49610 Minnesota 65
McGregor, MN
55760

PROPERTY INFORMATION

Location: 49610 Minnesota 65
McGregor
Tax ID: 29-0-035100

Use: Residential, Cabin
System Design Flow: 450
GENERAL SYSTEM TYPE: Sand Filter 1x yr NO TEST

Fold
Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 09/27/2024 - Inspection Type: ROUTINE - Correction Status: No corrections needed

Company:
Septic Check

Work Performed By:
Kyle Wade

Submitted 09/30/2024 by:
Heather Johnson

Fold
Here

COMMENTS & GENERAL INSPECTION NOTES

No Deficiencies Noted

Pumps, floats and alarms tested and working properly.
Flow meter on septic tank pump read 38.8 gallons per minute.
We flushed the laterals on the sand filter. Solids levels in the tanks do not indicate the need for pumping at this time. Everything is in good working order.

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
Components accessible for service:	YES
All required service performed (if no - specify omitted inspection items in notes):	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 2 Compartment

Manufacturer: Unknown

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	2	
Compartment 2 Scum accumulation (Inches, if other specify):	0	
Compartment 2 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

Panel: Control - 2 Pumps

This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	40 sec	
Pump 1: off hours (override in parentheses - if present):	1	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	15844	
Pump 1: Cycle Count (override in parentheses - if present):	26321	
Pump 2: on minutes (override in parentheses - if present):	2 min 45 sec	
Pump 2: off hours (override in parentheses - if present):	8	
Pump 2: gallons per dose (override in parentheses - if present):	-	
Pump 2: ETM hours (override in parentheses - if present):	20517	
Pump 2: Cycle Count (override in parentheses - if present):	22051	

Pump: Effluent Pump

Manufacturer: Goulds Pumps

This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	

Pump: Effluent Pump		
Manufacturer: Goulds Pumps		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
TANK: Pump Basin Sand Filter Basin		
This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	
Media Filter: Recirculating Sand Filter 12X30 OSI Sand Filter		
This component was:	Fully Inspected	
Ponding present? If YES explain in comments:	NO	
Average squirt height (if performed) (feet, if other specify):	-	
Lateral lines flushed:	YES	
Media Filter: Mound, Manufacturer= Site Constructed - Gravel Bed 10X32 Rockbed		
Manufacturer: Site Constructed Model: Gravel Bed		
This component was:	Fully Inspected	
Slope integrity maintained:	N/A	
Lateral lines flushed:	NO	
Ponding present? If YES explain in comments:	NO	
Average squirt height (if performed) (feet, if other specify):	-	