

SAMPLING REPORT

Location: 43696 - 245th Place

McGregor

14-0-024400 & 14-1-068600

Owner: Covenant Pines Bible Camp - Bald Eagle

Use: Other

Service Company:

Septic Check

6074 Keystone Rd

Milaca, MN 56353

320-983-2447

Sample Date: 07/14/2023 Sample entered by: Heather Johnson Report submitted: 11/07/2023

Notes:

ONSITE SEWAGE SYSTEM SAMPLING DETAIL

COMPONENT	TYPE	SAMPLE	LIMIT	RESULT
Control - 1 Pump - Drainfield Dose Panel	Effluent	Flow	5,800 GPD	372.19

This report indicates certain characteristics of the sample taken at the time of visit. In no way is this report a guarantee of operation or future performance.

SAMPLING REPORT

Location: 43696 - 245th Place

McGregor

14-0-024400 & 14-1-068600

Owner: Covenant Pines Bible Camp - Retreat Center

Use: Other

Service Company:

Septic Check

6074 Keystone Rd

Milaca, MN 56353

320-983-2447

Sample Date: 07/14/2023 Sample entered by: Heather Johnson Report submitted: 11/07/2023

Notes:

ONSITE SEWAGE SYSTEM SAMPLING DETAIL

COMPONENT	TYPE	SAMPLE	LIMIT	RESULT
Control - 2 Pumps - Drainfield Dose Panel	Effluent	Flow	5800 GPD	4996.12

This report indicates certain characteristics of the sample taken at the time of visit. In no way is this report a guarantee of operation or future performance.

SAMPLING REPORT

Location: 43696 - 245th Place

McGregor

14-0-024400 & 14-1-068600

Owner: Covenant Pines Bible Camp - Retreat Center

Use: Other

Service Company:

Septic Check

6074 Keystone Rd

Milaca, MN 56353

320-983-2447

Laboratory:AW Labs

Sample Date: 10/10/2023 Sample entered by: Heather Johnson Report submitted: 11/07/2023

Notes:

ONSITE SEWAGE SYSTEM SAMPLING DETAIL

COMPONENT	TYPE	SAMPLE	LIMIT	RESULT
Pump Tank -1,500 Gal Drainfield Dose Tank	Effluent	CBOD	< 175 MG/L	2.07
Pump Tank -1,500 Gal Drainfield Dose Tank	Effluent	Fecal	< 1,000 MG/L	3260 -Limit Exceeded
Pump Tank -1,500 Gal Drainfield Dose Tank	Effluent	FOG	< 30 MG/L	<5
Pump Tank -1,500 Gal Drainfield Dose Tank	Effluent	pH	< 30 MG/L	6.5
Pump Tank -1,500 Gal Drainfield Dose Tank	Effluent	TSS	< 65 MG/L	1.6
Pump Tank -1,500 Gal Drainfield Dose Tank	Effluent	TKN	< 30 MG/L	24.3

This report indicates certain characteristics of the sample taken at the time of visit. In no way is this report a guarantee of operation or future performance.

Septic Check

6074 Keystone Rd
Milaca, MN 56353

320-983-2447
Fax: 320-983-2151

Mail To: Covenant Pines Bible Camp - Bald Eagle
43969 - 245th Place
McGregor, MN
55760

PROPERTY INFORMATION

Location: 43696 - 245th Place
McGregor
Tax ID: 14-0-024400 &

Use: Commercial, Other
System Design Flow: 5800
GENERAL SYSTEM TYPE: Standard Comm 1 NO test

Fold
Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 07/16/2024 - Inspection Type: ROUTINE - Correction Status: No corrections needed

Company:
Septic Check

Work Performed By:
Kyle Wade

Submitted 07/23/2024 by:
Heather Johnson

Fold
Here

COMMENTS & GENERAL INSPECTION NOTES

No Deficiencies Noted

Sections NOT on the report/contract: Hydra system
*Septic scum=0 sludge=3 P1 etm=2.40.08 cc=33
**Treatment=scum=0 sludge=1 P2 etm=2.30.03 cc=31
***Clarifier W/effluent filter=scum=0 sludge=2 minutes on=5 off= 2 hrs 55 minutes
****Pump tank= scum=0 sludge= 0

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
Components accessible for service:	YES
All required service performed (if no - specify omitted inspection items in notes):	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Bald Eagle

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	5	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Bald Eagle

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Round Lake Bath House - Tank 1

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Round Lake Bath House - Tank 2

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Round Lake Bath House - Tank 3

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 2,500 Gal Septic Tank - Cabins

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	7	
Pumping recommended:	NO	

TANK: Pump Tank - 2,500 Gal Pump Tank 1

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

TANK: Pump Tank - 2,500 Gal Pump Tank 2

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

Panel: Control - 1 Pump - Drainfield Dose Panel

This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	6 min	
Pump 1: off hours (override in parentheses - if present):	2 hrs	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	-	
Pump 1: Cycle Count (override in parentheses - if present):	68613	

Pump: Effluent Pump - Drainfield Dose Pump

This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	

Media Filter: Mound - 8' x 125' Rockbed

Manufacturer: Site Constructed

This component was:	Fully Inspected	
Slope integrity maintained:	YES	
Lateral lines flushed:	NO	
Ponding present? If YES explain in comments:	NO	
Average squirt height (if performed) (feet, if other specify):	-	

Septic Check

6074 Keystone Rd
Milaca, MN 56353

320-983-2447
Fax: 320-983-2151

Mail To: Covenant Pines Bible Camp - Retreat Center
43696 - 245th Place
McGregor, MN
55760

PROPERTY INFORMATION

Location: 43696 - 245th Place
McGregor
Tax ID: 14-0-024400 &

Use: Commercial, Other
System Design Flow: 5800
GENERAL SYSTEM TYPE: SAND Comm 1x w/Test

Fold
Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 07/16/2024 - Inspection Type: ROUTINE - Correction Status: Corrections in progress

Company:
Septic Check

Work Performed By:
Kyle Wade

Submitted 07/23/2024 by:
Heather Johnson

Fold
Here

COMMENTS & GENERAL INSPECTION NOTES

No Deficiencies Noted

**** I noticed root intrusion in the first 2 septic tanks at the Retreat Center. *****

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
Components accessible for service:	YES
All required service performed (if no - specify omitted inspection items in notes):	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 1 Compartment - Retreat Center - Septic Tank 1

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	3	
Compartment 1 Sludge accumulation (Inches, if other specify):	6	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - Retreat Center - Septic Tank 2

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - Retreat Center - Septic Tank 3

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

TANK: Pump Tank - 1,500 Gal Pump Tank

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

TANK: Pump Tank - 650 Gal Pump Tank, near gym dose to mound

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

TANK: Septic Tank - 2 Compartment - 1,500 Gal Tank - gym tank

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	3	
Compartment 2 Scum accumulation (Inches, if other specify):	0	
Compartment 2 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 2,500 Gal Septic Tank Kitchen

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	2	
Compartment 1 Sludge accumulation (Inches, if other specify):	7	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 2,500 Gal Septic Tank- kitchen

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	4	
Pumping recommended:	NO	

TANK: Recirculation Tank - Recirculation Tank

This component was:	Fully Inspected	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Compartment 2 Scum accumulation (Inches, if other specify):	1	
Compartment 2 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	

Panel: Control - 2 Pumps - Recirc Panel

This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	2 min	
Pump 1: off hours (override in parentheses - if present):	10 min	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	999999	
Pump 1: Cycle Count (override in parentheses - if present):	831920	
Pump 2: on minutes (override in parentheses - if present):	2 min	
Pump 2: off hours (override in parentheses - if present):	10 min	
Pump 2: gallons per dose (override in parentheses - if present):	-	
Pump 2: ETM hours (override in parentheses - if present):	999999	
Pump 2: Cycle Count (override in parentheses - if present):	831918	

Pump: Effluent Pump - Recirculation Pump

This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	

Pump: Effluent Pump - Recirculation Pump

This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	

Media Filter: Recirculating Sand Filter - 24' x 50' Sand Filter

This component was:	Fully Inspected	
Ponding present? If YES explain in comments:	N/A	
Average squirt height (if performed) (feet, if other specify):	-	
Lateral lines flushed:	NO	

TANK: Pump Tank -1,500 Gal Drainfield Dose Tank

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

Panel: Control - 2 Pumps - Drainfield Dose Panel		
This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	4 min	
Pump 1: off hours (override in parentheses - if present):	2 hrs	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	131687	
Pump 1: Cycle Count (override in parentheses - if present):	38854	
Pump 2: on minutes (override in parentheses - if present):	4 min	
Pump 2: off hours (override in parentheses - if present):	2 hrs	
Pump 2: gallons per dose (override in parentheses - if present):	-	
Pump 2: ETM hours (override in parentheses - if present):	133534	
Pump 2: Cycle Count (override in parentheses - if present):	38871	
Pump: Effluent Pump - Drainfield Dose Pump 1		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Pump: Effluent Pump - Drainfield Dose Pump 2		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Distribution: Automatic Distributing Valve		
Manufacturer: Orenco		
This component was:	Fully Inspected	
Distributing valve dosing as intended:	YES	
Media Filter: Mound - 4 Rockbeds - 75'x25' each		
Manufacturer: Site Constructed		
This component was:	Fully Inspected	
Slope integrity maintained:	YES	
Lateral lines flushed:	NO	
Ponding present? If YES explain in comments:	NO	
Average squirt height (if performed) (feet, if other specify):	-	

Septic Check

6074 Keystone Rd
Milaca, MN 56353

320-983-2447
Fax: 320-983-2151

Mail To: Covenant Pines Bible Camp - Retreat Center
43696 - 245th Place
McGregor, MN
55760

PROPERTY INFORMATION

Location: 43696 - 245th Place
McGregor
Tax ID: 14-0-024400 &

Use: Commercial, Other
System Design Flow: 5800
GENERAL SYSTEM TYPE: SAND Comm 1x w/Test

Fold
Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 07/16/2024 - Inspection Type: ROUTINE - Correction Status: Corrections in progress

Company:
Septic Check

Work Performed By:
Kyle Wade

Submitted 07/23/2024 by:
Heather Johnson

Fold
Here

COMMENTS & GENERAL INSPECTION NOTES

No Deficiencies Noted

**** I noticed root intrusion in the first 2 septic tanks at the Retreat Center. *****

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
Components accessible for service:	YES
All required service performed (if no - specify omitted inspection items in notes):	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 1 Compartment - Retreat Center - Septic Tank 1

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	3	
Compartment 1 Sludge accumulation (Inches, if other specify):	6	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - Retreat Center - Septic Tank 2

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - Retreat Center - Septic Tank 3

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

TANK: Pump Tank - 1,500 Gal Pump Tank

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

TANK: Pump Tank - 650 Gal Pump Tank, near gym dose to mound

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

TANK: Septic Tank - 2 Compartment - 1,500 Gal Tank - gym tank

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	3	
Compartment 2 Scum accumulation (Inches, if other specify):	0	
Compartment 2 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 2,500 Gal Septic Tank Kitchen

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	2	
Compartment 1 Sludge accumulation (Inches, if other specify):	7	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 2,500 Gal Septic Tank- kitchen

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	4	
Pumping recommended:	NO	

TANK: Recirculation Tank - Recirculation Tank

This component was:	Fully Inspected	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Compartment 2 Scum accumulation (Inches, if other specify):	1	
Compartment 2 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	

Panel: Control - 2 Pumps - Recirc Panel

This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	2 min	
Pump 1: off hours (override in parentheses - if present):	10 min	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	999999	
Pump 1: Cycle Count (override in parentheses - if present):	831920	
Pump 2: on minutes (override in parentheses - if present):	2 min	
Pump 2: off hours (override in parentheses - if present):	10 min	
Pump 2: gallons per dose (override in parentheses - if present):	-	
Pump 2: ETM hours (override in parentheses - if present):	999999	
Pump 2: Cycle Count (override in parentheses - if present):	831918	

Pump: Effluent Pump - Recirculation Pump

This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	

Pump: Effluent Pump - Recirculation Pump

This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	

Media Filter: Recirculating Sand Filter - 24' x 50' Sand Filter

This component was:	Fully Inspected	
Ponding present? If YES explain in comments:	N/A	
Average squirt height (if performed) (feet, if other specify):	-	
Lateral lines flushed:	NO	

TANK: Pump Tank -1,500 Gal Drainfield Dose Tank

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

Panel: Control - 2 Pumps - Drainfield Dose Panel		
This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	4 min	
Pump 1: off hours (override in parentheses - if present):	2 hrs	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	131687	
Pump 1: Cycle Count (override in parentheses - if present):	38854	
Pump 2: on minutes (override in parentheses - if present):	4 min	
Pump 2: off hours (override in parentheses - if present):	2 hrs	
Pump 2: gallons per dose (override in parentheses - if present):	-	
Pump 2: ETM hours (override in parentheses - if present):	133534	
Pump 2: Cycle Count (override in parentheses - if present):	38871	
Pump: Effluent Pump - Drainfield Dose Pump 1		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Pump: Effluent Pump - Drainfield Dose Pump 2		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Distribution: Automatic Distributing Valve		
Manufacturer: Orenco		
This component was:	Fully Inspected	
Distributing valve dosing as intended:	YES	
Media Filter: Mound - 4 Rockbeds - 75'x25' each		
Manufacturer: Site Constructed		
This component was:	Fully Inspected	
Slope integrity maintained:	YES	
Lateral lines flushed:	NO	
Ponding present? If YES explain in comments:	NO	
Average squirt height (if performed) (feet, if other specify):	-	

Septic Check

6074 Keystone Rd
Milaca, MN 56353

320-983-2447
Fax: 320-983-2151

Mail To: Covenant Pines Bible Camp - Bald Eagle
43969 - 245th Place
McGregor, MN
55760

PROPERTY INFORMATION

Location: 43696 - 245th Place
McGregor
Tax ID: 14-0-024400 &

Use: Commercial, Other
System Design Flow: 5800
GENERAL SYSTEM TYPE: Standard Comm 1 NO test

Fold
Here

ON-SITE WASTEWATER TREATMENT SYSTEM INSPECTION REPORT

Inspected: 07/16/2024 - Inspection Type: ROUTINE - Correction Status: No corrections needed

Company:
Septic Check

Work Performed By:
Kyle Wade

Submitted 07/23/2024 by:
Heather Johnson

Fold
Here

COMMENTS & GENERAL INSPECTION NOTES

No Deficiencies Noted

Sections NOT on the report/contract: Hydra system
*Septic scum=0 sludge=3 P1 etm=2.40.08 cc=33
**Treatment=scum=0 sludge=1 P2 etm=2.30.03 cc=31
***Clarifier W/effluent filter=scum=0 sludge=2 minutes on=5 off= 2 hrs 55 minutes
****Pump tank= scum=0 sludge= 0

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
Components accessible for service:	YES
All required service performed (if no - specify omitted inspection items in notes):	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Bald Eagle

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	5	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Bald Eagle

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Round Lake Bath House - Tank 1

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	2	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Round Lake Bath House - Tank 2

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 1,500 Gal Septic Tank - Round Lake Bath House - Tank 3

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

TANK: Septic Tank - 1 Compartment - 2,500 Gal Septic Tank - Cabins

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	7	
Pumping recommended:	NO	

TANK: Pump Tank - 2,500 Gal Pump Tank 1

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

TANK: Pump Tank - 2,500 Gal Pump Tank 2

Manufacturer: Local Manufacturer

This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	1	
Pumping recommended:	NO	

Panel: Control - 1 Pump - Drainfield Dose Panel

This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	6 min	
Pump 1: off hours (override in parentheses - if present):	2 hrs	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	-	
Pump 1: Cycle Count (override in parentheses - if present):	68613	

Pump: Effluent Pump - Drainfield Dose Pump

This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	

Media Filter: Mound - 8' x 125' Rockbed

Manufacturer: Site Constructed

This component was:	Fully Inspected	
Slope integrity maintained:	YES	
Lateral lines flushed:	NO	
Ponding present? If YES explain in comments:	NO	
Average squirt height (if performed) (feet, if other specify):	-	