Land Alteration App. # App-2022-009154, UID # 205782

- Submitted on 7/7/22
- Inspected on 7/15/22
  - Rip-rap was already installed
  - No erosion control after construction disturbance
  - Some rip-rap appears to be below OHW which DNR doesn't require a permit
  - With rip-rap being installed prior to an onsite inspection Henry could not determine if an active erosion problem existed
  - Would require a vegetative buffer to be established with issuance of any land alteration rip-rap permit



Pre-existing conditions per photo attached to application



Onsite inspection photo 7/15/22

Emerson, Kevin Hammal Lake

## Emerson, Kevin Hammal Lake



