

for Enbridge  
5/4/2006

- 100 BM Mill-Turn
- 94 Cur at 1/2 mile
- 935 Cur at 1/2 mile
- 1017 Bottom of RIB
- 98.7 Bottom of RIB
- 98.5 Pipe TL
- 11.8 Pipe H/d

