2011 purple code

Holding tank Design

www.SepticResource.com (vers 14.2)

					(**************************************
	Property Owner:	Dean Rasmussen	Date:	11/4/2019	
	Site Address:	20385 485th St.	PID:	29-1-104000	
	Comments: Steep slope and disturbed soils plus lot size are reasons for holding tank.				
	instructions:	= site specific input	= adjust if desired	= self-calcula	ated (DO NOT ADJUST)
1)	2 bedroom Type II Residential System				
2)	300 GPD design flow				
	No Lift station to holding tank (lift basket < 100 gal treat as sewer line, > 100 gal treat as tank)				
3)			1820 Gallon Holding	g tank (minimum)	at 40.00 gpi
4)	inches from bottom of tank to "Hi Level" float (75% full when alarm activates)				
5)	gallons reserve capacity (after High Level Alarm is activated)				
	I hereby certify that have completed this work in accordance with all applicable ordinances, rules and laws.				
	Roger Herri				11/4/2019
	Designer\Signature	Compa	iny		Date