

Home Owner: Chad Rasmussen
 Billing Address: 15164 Manitowish Trd. NE
Prior Lake, MN 55372
 Directions: 34097 605th Ln.
Hill City

Home Phone: _____
 Cell Phone: 612-708-2228

Work Phone: _____
 Date of Pumping: 7-25-23

Next Recommended Pump Date: 4 yrs July 2027
 Legal Dis. Or Pin # _____

Septic Installer Name, Phone #, Date of Installation:
McNeil

of Bedrooms: _____
 Type of Septic System (Circle One)
 Pressure Bed Trench Mound
 Other: _____

Septic Tank Location Reference to Non-moveable Object:
NE corner of house 35'

Type of Septic Tank (Circle One)
 Block Precast Plastic Steel Fiberglass

Septic Tank Volume: 1250 +/-

Is the Septic Tank Watertight and in Good Structural Condition?
 Yes No

Tank Baffle: _____

Depth to Riser: Surface

Effluent Filter: Yes No

Cleaned: Yes No

Test Pump and Alarm Good Needs Repair

Time Dosing or On Demand _____

Pipe Settling or Movement: _____

Comments: _____

*paid 7/31/23
 check #
 8806*

Drivers name: Bill

Homeowner's Signature _____

RONALD MYERS

DOING BUSINESS AS

EXTRACTOR

32731 Woodland Park Road
 Grand Rapids MN, 55744
 Phone # 218-327-9273 or 218-259-9273

Treatment Location: WWTP Site 1 2 3 4 5

Was the Septic Tank Pumped Through the
 Maintenance hole (7080.0175)? Yes No

If no maintenance hole exists on a sewage tank, the owner or the owner's agent shall install maintenance holes in sewage tanks in accordance with part 7080.0130, subpart 2, item M, subitem (1), to allow for maintenance to take place through the maintenance hole. If the owner or owner's agent refuses to allow the removal through a maintenance hole, the licensed pumper must obtain a signed statement from the owner or owner's agent that the owner or agent was informed of correct removal procedures and the reason for refusal.

Reason (Circle One):
 No maintenance hole
 Home owner refused access to manhole
 No manhole
 Ground was frozen, emergency pumping
 Other: _____

Pumping		250.00
Materials		
Line Cleaning		
Thawing		
Mileage		56.00
Disposal Fee		
_____ Holding tank		
_____ Septage		
Other		
TOTAL		306.00