Preliminary & Field Evaluation Form Tank Replacement www.Se

www.SepticResource.com vers 12.4

Owner Information						
Date	10/6/2023			Sec / Twp / Rng	S-4, T-46, R-27	
Parcel ID	07-1-152400			LUG (county, city, township)	Aitkin Co.	
Property Owner:	Bryan Murdoff			Owners address (if different)		
Property Address:	43007 333rd Ln. Aitkin MN 56431			5790 Drake Dr		
City / State / Zip:				Independence MN 55359		
				-		-
Flow Information and Waste Type / Strength						
Estimated Design f	low 300			Anticipated Waste strength		
		_			Hi Strength	✓ Domestic
Comments: Septic				Any Non-Domestic Waste	Yes (class V)	✓ No
Existing Install 1650 Jaco	g Mound is Com obson 2/Compart			Sewage ejector/grinder pump	Yes	✓ No
Tunk.			Water softener	Yes	✓ No	
				Garbage Disposal	Yes	✓ No
				Daycare / In home business	Yes	✓ No
Site Information						
Existing & propose improvements locar		Yes	✓ No	Well casing depth	Existing deep	well
Easements on lot lo (see site map)	ocated	Yes	✓ No	Drainfield w/in 100' of residential well	✓ Yes	☐ No
Property lines deter (see site map)	mined	✓ Yes	☐ No	Site w/in 200' of transient noncommunity water supply (T	Yes	✓ No
Req'd setbacks dete (see site map)	ermined	✓ Yes	☐ No	Site w/in an inner wellhead mgmt zone (CWS/NTNCWS)	Yes	☐ No
Utilities located & (gopher state one call		Yes	✓ No	Buried water supply pipe w/in 50' of system	Yes	✓ No
Access for system (shown on site map)	maintenance	✓ Yes	☐ No	Site located in Shoreland (w/in 1000' of lake, 300' of river)	✓ Yes	☐ No
Soil treatment area	protected	✓ Yes	☐ No	Site map prepared with previous items included	✓ Yes	☐ No
Construction relate	Replace is same location, slightly different angle.					
		Tight between	en house an	d mound rockbed.		

		Soil Information	gi she	
Tank Replace	Evidence of site: Cut Filled Compacted	Yes Yes Yes	☐ No ☐ No ☐ No	
Original soils	Yes No	Disturbed O	Yes Yes	☐ No
Soil logs completed and attached	Yes No	Perk test completed and attached (if applicable)	Yes	☐ No
Soil loading rate (gpd/ft ²)		Percolation rate (if applicable)	<u>u</u>	
Depth/elev to SHWT		Flooding or run-on potential (comments)	Yes	☐ No
Depth to system bottom maximum (or elev minimum) Depth/elev to standing water (if applicable) Depth/elev to bedrock (if applicable) Soil Survey information determined (see attachment) Differences between soil survey	Yes No	Flood elevation (if applicable) Elevation of ordinary high water level (if applicable) Floodplain designation and elev - 100 yr/10 yr (if applicable)		
and field evaluation (if applicable)				
0 1/1		ordance with MN 7080 and any local reg's.		1.4247
Designal Signature		Brummer Septic LLC. Company		L-1347 License #

{ Tank Replacement Notes }

Property Owner:	Bryan Murdoff		Date: 10/6/2023	Designer's Initials:	JB
Parcel ID. Number :	07-1-152400	Address :			
Toul Doule					

Tank Replacement

- 1 Existing mound is Compliant (9/25/2023), reuse mound.

 System and tank will meet Deep well setbacks, house setback, wetland setback, lake setback.
- 2 See note from Aitkin Co on lake setback measurement. (Pages 7 & 8)
- 3 Pump and remove existing tank. Very tight to existing mound. May reuse 2" supply pipe if possible. Keep new tank 10 ft from house, will be 53 ft from deep well. Install cleanout at connection to existing sewer pipe. Air test required less than 50 ft to deep well.
- 4 Order 1650 Jacobson 2/Compartment tank with side inlet.
 Install tank parallel to house, close to same location as old tank.
 May install tank higher, and landscape cover soil to shed surface water away from tank location.
 Insulate top of tank. Install pump capable of 25 GPM at 20 ft of head, install electric alarm.
- 5 Existing rockbed install notes 10' x 25', 3 laterals, 1/4" perfs spaced 30" apart Approx. 33 perfs x .74 gpm = 24.4 GPM
- 6 Raise manholes to above finished grade, recommend 4" above finished grade.
- 7 The bench mark is the nail on the tree near Deep Well area, BM = Elv. 100'.
 Installer to double check bench mark. Installer should confirm bench mark and sand height Elv. with inspector.
 Installer should record bench mark Elv. and sand height on installation inspection form.
 Top of Deep Well Cap Elv. = 100'
- 8 The Jacobson 1650 compartment tank will be gravity flow from dwelling. Install the pump for 6 demand doses per day. approx. 50 gallons per dose, 3.9 inches of tank level. Install alarm at 3 inches from pump on level. Connect to existing mound 2" supply pipe, make sure pipe drains back to pump tank.

No Warranty or guaranty on condition of mound.

Recommend Installing an Effluent filter and Alarm on septic tank outlet.

MPCA Recommends installing an event counter on all systems with a pump.

Designed to Aitkin Co. and MPCA recommendations and requirements.

Designer Signature Design Company License# L-1347
Brummer Septic LLC.

Property Owner: Bryan Murdoff Date: 10/6/2023 Designer's Initials: JB Parcel ID. Number: 07-1-152400 Address: 43007 333rd Ln. Aitkin MN 56431 Aitkin Co. One Inch =20 ft.' EXisting BockBed 0 0 Tuck Deck House Decle Bench Mark Oak Tree

Nail at Elv = 100

Elv. Of ground at New Septic Tank = 97.5' Estimated New Inlet Septic Tank Elv. = 96.5' Top of Existing 2" supply Pipe Elv.= 96.8' Top of Existing sewer pipe at house Elv.= 97.4'


Bench Mark Elv. =100 ' Top of Deep Well Cap Ground at well Elv. = 98.3'

Grade at NE corner of house Elv.= 99.1' Grade near Center of mound Elv.= 97.4' Elv. Of Top of rock bed Elv. = 96.6'


Estimated Wetland Elv.= 85'

1650 Gallon 2 Compartment Septic Tank

TOP VIEW



Drawings Owned BY Jacobson Precast, Inc. 36641 HWY 169, Aitkin, Mn 56431





Wood/Murdoff 1 message	
Connor Plagge <connor.plagge@co.aitkin.mn.us> To: "brummerseptic@gmail.com" <pre></pre></connor.plagge@co.aitkin.mn.us>	Thu, Sep 28, 2023 at 4:26 PM
Hey Jeff,	

I have attached the document you requested about the Murdoff/Wood Property. It appears the wetland to the East is not classified as Lake Four and the setback would not apply in that area. I have attached an image where the setbacks would apply and the distances from the house to the OHWL.

Please let me know if I can do anything else.

Thank you,

Connor Plagge

Aitkin County Planning & Zoning

Zoning Officer

307 2nd Street NW

Aitkin, MN 56431

218-927-7378

connor.plagge@co.aitkin.mn.us

all attachments) is confidential and intended solely for the use of the addressee(s). If you have received this transmission in error, please notify the sender by reply and delete this transmission immediately. Any unauthorized distribution, or copying of this transmission, or misuse or wrongful disclosure of information contained in it, is strictly prohibited. The information contained in this document is provided on an as-is basis and does not constitute a binding legal contract or receipt for services.

Murdoff_Wood_Property.pdf





Detailed Parcel Report

Parcel Number: 07-1-152400

General Information

Township/City:

FARM ISLAND TWP

Taxpayer Name:

WOOD, BETHANY & MURDOFF, BRYAN

Taxpayer Address:

5790 DRAKE DR

INDEPENDENCE MN 55359

Property Address:

43007 333rd Ln

Township:

46

Lake Number:

1016200

Range:

27

Lake Name:

FOUR LAKE IVE

JUK LAN

Section:

4

Acres:

0.00

Green Acres:

No

School District:

1.00

Plat:

BLUE RIDGE ESTATES

Brief Legal Description:

LOT 12 BLK 5

Tax Information

Class Code 1:

Non-Comm Seasonal Residential Recreational

Class Code 2:

Unclassified

Class Code 3:

Unclassified

Homestead:

Non Homestead

Assessment Year:

2023

Estimated Land Value:

\$111,800.00

Estimated Building Value:

\$120,200.00

Estimated Total Value:

\$232,000.00

Prior Year Total Taxable Value:

\$196,200.00

Current Year Net Tax (Specials Not Included):

\$1,108.00

Total Special Assessments:

\$0.00

**Current Year Balance Not Including Penalty:

\$554.00

Delinquent Taxes:

No

^{*} For more information on delinquent taxes, please call the Aitkin County Treasurer's Office at 218-927-7325.

^{**} Balance Due on a parcel does not include late payment penalties.