

FIELD EVALUATION SHEET

PRELIMINARY EVALUATION DATE: June 21, 16, FIELD EVALUATION DATE
PROPERTY OWNER: Judi Reed PHONE 763-257-6673
ADDRESS: 44541 298th Lane CITY, STATE, ZIP: Arden MN 56431
LEGAL DESCRIPTION: 07-1-099800 & 07-1-099900
PIN# SEC T R TWP NAME Farm Island
FIRE# LAKE/RIVER LAKE CLASS OHWL FT.

DESCRIPTION OF SOIL TREATMENT AREAS

	AREA #1	AREA #2	REFERENCE BM ELEV. FT	REFERENCE BM DESCRIPTION
DISTURBED AREAS	YES NO	YES NO		
COMPACTED AREAS	YES NO	YES NO		
FLOODING	YES NO	YES NO		
RUN ON POTENTIAL	YES NO	YES NO		
SLOPE %				
DIRECTION OF SLOPE				
LANDSCAPE POSITION				
VEGETATION TYPES				

DEPTH TO STANDING WATER OR MOTTLED SOIL: BORING# 1, 1A, 2, 2A

BOTTOM ELEVATION--FIRST TRENCH OR BOTTOM OF ROCK BED: #1 FT., #2 FT.

SOIL SIZING FACTOR: SITE #1, SITE #2

CONSTRUCTION RELATED ISSUES: Tank replacement only - existing is cracked

LIC# 698/1672 SITE EVALUATOR SIGNATURE: [Signature]

SITE EVALUATOR NAME: Mark P Rutter TELEPHONE# 927.4125

LUG REVIEW [Signature] 6-28-16 DATE

Comments:

SOIL BORING LOGS ON REVERSE SIDE

APPROVED
ON SITE INSPECTION
ON SITE INSPECTION
NO ON SITE INSPECTION
DATE 6-27-16 [Signature]

1 of 2

2 of 2

6-27-16

On/Off

6-27-16 (KT)

Don't think Tank is shared between 2 property
 Tank meets 50' setback from both wells
 Installing new 1,800 septic/1st tank back
 raising existing alarm/pump & treating back
 into existing drainfield.

