

34918 444th Pl. Aitkin MN 56431

Soil Log #2

<input checked="" type="checkbox"/> Boring <input type="checkbox"/> Pit		Elevation <u>97.8'</u>		Depth to SHWT <u>12"</u>			
Depth (in)	Texture	fragment %	matrix color	redox color	consistence	grade	shape
0 - 6	Topsoil Sandy Loam	<35	10YR3/2		Loose	Loose	Granular
6 - 12	Silt Loam	<35	10YR4/4	E Horizon	Loose	Loose	Granular
12 - 16	Silt Loam	<35	10YR5/4 mixed with 7.5yr4/4	Start of a limiting layer	Friable	Weak	Blocky
16-20	Clay Loam	<35	7.5YR4/4		Friable	Moderate	Platy
		<35			Loose	Loose	Granular

34918 444th Pl. Aitkin MN 56431

Soil Log #3

<input type="checkbox"/> Boring <input type="checkbox"/> Pit		Elevation _____		Depth to SHWT _____			
Depth (in)	Texture	fragment %	matrix color	redox color	consistence	grade	shape
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive

I hereby certify this work was completed in accordance with MN 7080 and any local req's.

Designer Signature 

Brummer Septic LLC.
Company

L-1347
License #