The state of the s	SILVE AND SILVE		Soil Information		
Original soils	☑ Yes	□No	Evidence of site:  Cut  Filled  Compacted  Disturbed	☐ Yes ☐ Yes ☐ Yes ☐ Yes	☑ No ☑ No ☑ No ☑ No
Soil logs completed and attached	☑ Yes	□No	Perk test completed and attached (if applicable)	☐ Yes	☑No
Soil loading rate (gpd/ft <sup>2</sup> )	0.60	0	Percolation rate (if applicable)		
Depth/elev to SHWT	12'		Flooding or run-on potential (comments)	☐Yes	☑ No
Depth to system bottom maximum (or elev minimum)	(+24	")			
Depth/elev to standing water (if applicable)			Flood elevation (if applicable)		
Depth/elev to bedrock if applicable)			Elevation of ordinary high water level (if applicable)		
Soil Survey information determined (see attachment)	☑ Yes	□ No	Floodplain designation and elev - 100 yr/10 yr (if applicable)		
Differences between soil survey and field evaluation (if applicable)					

I hereby certify this evaluation was complete	ed in accordance with MN 7080 and any local reg's.	
O. Sal Domens	Brummer Septic LLC.	L-1347
Designer Signatury	Company	License #