

36374 Nature Ave. Aitkin MN 56431

**Soil Log #2**

<input checked="" type="checkbox"/> Boring <input type="checkbox"/> Pit		Elevation <u>97.9'</u>		Depth to SHWT <u>14"</u>			
Depth (in)	Texture	fragment %	matrix color	redox color	consistence	grade	shape
0 - 6	Topsoil Sandy Loam	<35	10YR3/2		Loose	Loose	Granular
6 - 14	Loam	<35	7.5YR5/4		Friable	Loose	Granular
14 - 18	Loam	<35	7.5YR5/4	7.5YR5/6 & 7.5YR6/2	Friable	Loose	Granular
18	Clay	<35	5YR5/3		Firm	Moderate	Platy
		<35					

36374 Nature Ave. Aitkin MN 56431

**Soil Log #3**

<input type="checkbox"/> Boring <input type="checkbox"/> Pit		Elevation _____		Depth to SHWT _____			
Depth (in)	Texture	fragment %	matrix color	redox color	consistence	grade	shape
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive

I hereby certify this work was completed in accordance with MN 7080 and any local req's.

  
 \_\_\_\_\_  
 Designer Signature

Brummer Septic LLC.  
 \_\_\_\_\_  
 Company

L-1347  
 \_\_\_\_\_  
 License #