

Soil Information

		Evidence of site:	
		Cut	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
		Filled	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
		Compacted	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
		Disturbed	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Original soils	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Soil logs completed and attached	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Perk test completed and attached (if applicable)	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Soil loading rate (gpd/ft ²)	<u>0.60</u>	Percolation rate (if applicable)	_____
Depth/elev to SHWT	<u>7"</u>	Flooding or run-on potential (comments)	<input type="checkbox"/> Yes <input type="checkbox"/> No
Depth to system bottom maximum (or elev minimum)	<u>(+ 36")</u>	Flood elevation (if applicable)	<u>1202.7</u>
Depth/elev to standing water (if applicable)	_____	Elevation of ordinary high water level (if applicable)	_____
Depth/elev to bedrock (if applicable)	_____	Floodplain designation and elev - 100 yr/10 yr (if applicable)	<u>1202.7 - 100 yr</u> <u>1199.8 - 10 yr</u>
Soil Survey information determined (see attachment)	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Differences between soil survey and field evaluation (if applicable)	_____ _____		

I hereby certify this evaluation was completed in accordance with MN 7080 and any local req's.


Designer Signature

Brummer Septic LLC.
Company

L-1347
License #