

41427 390th St. Aitkin MN 56431

Soil Log #2

<input checked="" type="checkbox"/> Boring <input type="checkbox"/> Pit		Elevation <u>1200.7'</u>		Depth to SHWT <u>7"</u>			
Depth (in)	Texture	fragment %	matrix color	redox color	consistence	grade	shape
0 - 7	Topsoil	<35	10YR3/2		Friable	Weak	Blocky
7 - 13	Clay Loam	<35	2.5Y5/2	7.5YR5/6	Friable	Weak	Blocky
		<35			Loose	Loose	Granular
		<35			Loose	Loose	Granular
		<35			Loose	Loose	Granular

41427 390th St. Aitkin MN 56431

Soil Log #3

<input type="checkbox"/> Boring <input type="checkbox"/> Pit		Elevation _____		Depth to SHWT _____			
Depth (in)	Texture	fragment %	matrix color	redox color	consistence	grade	shape
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive

I hereby certify this work was completed in accordance with MN 7080 and any local req's.


 Designer Signature

Brummer Septic LLC.
 Company

L-1347
 License #