

41902 251st Pl. McGregor MN 55760

Soil Log #2

Boring Pit

Elevation 96.9'

Depth to SHWT 84"

Depth (in)	Texture	fragment %	matrix color	redox color	consistence	grade	shape
0 - 7	Topsoil Sandy Loam	<35	10YR3/2		Loose	Loose	Granular
7 - 21	Med Sand	<35	10YR5/6		Loose	Loose	Granular
21 - 63	Med Sand	<35	10YR6/4		Loose	Loose	Granular
63 - 84	Med Sand	<35	10YR7/4		Loose	Loose	Granular
		<35			Loose	Loose	Granular

41902 251st Pl. McGregor MN 55760

Soil Log #3


Boring Pit

Elevation _____

Depth to SHWT _____

Depth (in)	Texture	fragment %	matrix color	redox color	consistence	grade	shape
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive
		<35 35 - 50 >50			loose friable firm rigid	loose weak moderate strong	single grain granular blocky prismatic platy massive

I hereby certify this work was completed in accordance with MN 7080 and any local req's.

Designer 

Brummer Septic LLC.
Company

L-1347
License #