Customer Name: Dale Gillson

Date: Lucas School

Tests By: Enter Company Name

DRP: Enter Company DRP

MPCA License No:

Site Address:

Legal Description:

hill lake

Site Elevations

nchmark: bottom of hill	Transit Read	ding:	3.42	Ft	Elevation:	100	Ft
Description	Reading (Ft)	Elevation (Ft))			
up side of proposed mound	3.42	100					
down side of rock bed	4.83	9	8.59				
20 ft down slope from rock bed	6.5	9	6.92				
20ft down slope south end	7.25	9	6.17				
bottom of rock bed	0.42		103				
pump hight	0.42		103				
dis pipe	-0.92	10)4.34				
tank inlet existing	-3.2	10	06.62				

Site Slopes

Description	Distance (Ft)	Drop (Ft)	Slope (%)
up side of proposed mound to down side of rock bed	10	1.4	14
up side of proposed mound to 20 ft down slope from ro	c 30	3.1	10.3
up side of proposed mound to 20ft down slope south en	ad 30	3.8	12.7
tank inlet existing to dis pipe	30	2.3	7.7