

# Soil Observation Log

www.SepticResource.com vers 12.4

Owner Information	
Property Owner / project: <u>LUCAS AND STEPHANE SCHOEN</u>	Date <u>9/4/2021</u>
Property Address / PID: <u>67161 348TH PL</u>	

Soil Survey Information		<input type="checkbox"/> refer to attached soil survey
Parent mat'l's:	<input type="checkbox"/> Till <input checked="" type="checkbox"/> Outwash <input type="checkbox"/> Lacustrine <input type="checkbox"/> Alluvium <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Bedrock	
landscape position:	<input type="checkbox"/> Summit <input type="checkbox"/> Shoulder <input type="checkbox"/> Side slope <input checked="" type="checkbox"/> Toe slope	
soil survey map units:	<u>204C 198:</u>	slope <u>20</u> % direction- <u>downhill</u> <span style="color: green;">Toe up</span> <span style="color: green;">12% Toe Down</span>

Soil Log #1							
Depth (in)	Texture	<input type="checkbox"/> Boring <input checked="" type="checkbox"/> Pit fragment %	Elevation _____	matrix color	redox color	Depth to SHWT <u>6IN</u>	consistence    grade    shape
6	Topsoil	<35		2/1 10YR			Friable    Moderate    Blocky
7	Clay Loam	<35 35 - 50 >50		5/2 10YR	5/8 7.5YR		Firm    Strong    Platy
		<35 35 - 50 >50					loose friable firm rigid    loose weak moderate strong    single grain granular blocky prismatic platy massive
		<35 35 - 50 >50					loose friable firm rigid    loose weak moderate strong    single grain granular blocky prismatic platy massive
		<35 35 - 50 >50					loose friable firm rigid    loose weak moderate strong    single grain granular blocky prismatic platy massive

Comments: Brain Has Been on site already/