

Percolation Test & Design

For: Round Lake Resort

Location: 16469 Goshawk ST. McGregor

PID# 29-0-05461

Liability of Perc Test Limited to the Cost of Perc Test

Any extra design work or changes could result in extra charges

The results of this testing does not approve or disapprove this site for building construction or septic system installation. This testing information should be submitted to the approving officials for formal Review and approval while test holes are clearly staked

Some type of visible barrier should be provided to protect the proposed treatment area from construction traffic encroaching into this area and possible destroying the soil structure within the area.

Percolation Test Done By:

AT,Septic Inspection & Design Inc.

49861 Government Rd

Rush City MN 55069

320-980-0235

MPCA# 3886

Date: 10/9/2020

Revised 8/20/2022 *AT*

DESIGN APPROVED
AS PRESENTED

TOM ESPERSEN
CONTRACT INSPECTOR
LIC 1719 9/5/23