



PO Box 229 Zimmerman MN 55398
763-760-4172 Cert#9575 Lic#3974
arkseptic17@gmail.com

Date: 11/7/24

Contractor/Homeowner: Monte and trang Kuefler

Address: 18935 329th Pl

City: Isle Zip:56342

To Aitkin County:

Once a year monitoring plan:

-toe of mound was dry all around

-event counter is at 42180000


-effluent filter is clean

-tank looked good and functioning properly, dose not appear to need pumping at this time.

-lift pump and alarm are functioning.

Everything is visually functioning at this time, no signs of any failure. Pictures are attached. I believe this system is function properly and would recommend regular maintenance and that a monitoring plan is not needed moving forward from my findings today.

If you have any questions feel free to call me at 763-760-4172.



Ashley Krause/ARK SEPTIC LLC
MPCA LIC# 3974



00008174

00008174