

SAMPLING REPORT

Location: 36040 Hwy 65

McGregor

30-0-033300

Owner: Mille Lacs Corporate Ventures

Use: Other

Service Company:

Septic Check

6074 Keystone Rd

Milaca, MN 56353

320-983-2447

Sample Date: 08/13/2024 Sample entered by: Heather Johnson Report submitted: 08/15/2024

Notes:

ONSITE SEWAGE SYSTEM SAMPLING DETAIL

COMPONENT	TYPE	SAMPLE	LIMIT	RESULT
Control - 2 Pumps Mound Demand Dose Control F	Effluent	Flow	2400	269.91

This report indicates certain characteristics of the sample taken at the time of visit. In no way is this report a guarantee of operation or future performance.