

Yearly Monitoring Report

To: Aitkin County Planning and Zoning

From: Jerry Farley

Permit No. 222

Parcel I.D. : 29-0-013004

Permittee: Cheryl Raushel

Address : 50476 214th. Pl.,McGregor,Mn.55760

This Past fall of 2023 we made some changes to this system that will help to keep it from freezing. I replace the 2' sch. 40 pipe coming out of tank going to the drain field with insulated pipe with 6' of insulation on top of that. I moved the control panel over to the edge of the drive way wear it is easier to get to take the readings and use the panel. While I was there' I had all of the tanks pumped and they are in good condition. This past winter the system did not freeze but it was a mild winter.

No other changes have been made and the system is working as it Should.

I have been monitoring the event counter at the dose panel and the water usage is still average out to 100-150 gallons per day.

I walked around the treatment area and there are no signs of leakage.

In conclusion this system is working normal and I will continue to monitor it.

Signed by: Jerry Farley

Date; 07/22/2024

Lic. # L-1919