

SAMPLING REPORT

Location: 19585 484th St
McGregor
29-1-151300

Owner: Lorrie Moline
Use: Cabin

Service Company:

Septic Check

6074 Keystone Rd
Milaca, MN 56353
320-983-2447

Laboratory: A W Labs

Sample Date: 09/19/2024 Sample entered by: Heather Johnson Report submitted: 09/20/2024

Notes: Flow is from 8/23/2024 through 9/16/2024

ONSITE SEWAGE SYSTEM SAMPLING DETAIL

COMPONENT	TYPE	SAMPLE	LIMIT	RESULT
Effluent Pump Sand filter dose tank	Effluent	Fecal	<1000-100ml	<100
Effluent Pump septic tank pump	Effluent	Flow	450 gpd	23.1