

# SAMPLING REPORT

Location: 48702 - 187th Place  
McGregor  
**29-1-508200**

Owner: Jeff Gelo  
Use: Single Family

## Service Company:

**Septic Check**  
6074 Keystone Rd  
Milaca, MN 56353  
320-983-2447

Sample Date: 08/06/2024 Sample entered by: Heather Johnson Report submitted: 08/07/2024

Notes:

## ONSITE SEWAGE SYSTEM SAMPLING DETAIL

COMPONENT	TYPE	SAMPLE	LIMIT	RESULT
Control - 1 Pump Drainfield Dose Pump	Effluent	Flow	<450 gpd	50.1

*This report indicates certain characteristics of the sample taken at the time of visit. In no way is this report a guarantee of operation or future performance.*