

OSTP Soil Observation Log

Project ID:

1



Client/ Address: 67119 348th P1 Legal Description/ GPS: 12-0-023304

Soil parent material(s): (Check all that apply) Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape

Landscape Position: (check one) Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Vegetation: Wooded Soil survey map units: 204 B Slope: 3% Elevation:

Weather Conditions/Time of Day: 10 AM Clear Date: 10-16-24

Observation #/Location: Parcel e Observation Type: PIT

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure		
							Shape	Grade	Consistence
6	Loam	735	10YR 3/2				granular	weak	friable
107	Silt loam	735	10YR 6/4				granular	weak	friable
18	Silt loam	735	10YR 6/4	10YR 5/3			granular	weak	friable

Comments

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

David Laake (Designer/Inspector) Do Laake (Signature) 11774 (License #) 10-16-24 (Date)

OSTP Soil Observation Log

Project ID:



Client/ Address: Lot 119 348th place Legal Description/ GPS: 12-0-033 04

Soil parent material(s): (Check all that apply) Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape

Landscape Position: (check one) Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Vegetation: Wooded. Soil survey map units: _____ Slope%: 3 Elevation: _____

Weather Conditions/Time of Day: 10 AM clear Date: 10-16-24

Observation #/Location: _____ Observation Type: Pit

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Observation Type: _____		
							Shape	Grade	Consistence
5	Loam	735	10 Y/R 3/2				granular	Weak	friable
14	S th Loam	735	10 Y/R 6/4				granular	Weak	friable
15	S th Loam	735	10 Y/R 6/4	10 Y/R 5/8			granular	Weak	friable

Comments: _____

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

(Designer/Inspector) David Lauck _____

(Signature) _____

(License #) 1174 _____

(Date) 10/16/24



Client/ Address: 67119 348th Pl Legal Description/ GPS: 12-0-023304

Soil parent material(s): (Check all that apply) Summit Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Landscape Position: (check one) Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape

Vegetation: Wooded Soil survey map units: 24R Slope%: 3 Elevation:

Weather Conditions/Time of Day: 10 AM clear Date: 10-16-24

Observation #/Location: Parcel C Observation Type: Pit

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure		
							Shape	Grade	Consistence
5	Loam	735	10YR 3/2				granular	weak	friable
14	Silty Loam	735	10YR 6/4				granular	weak	friable
15	Silty Loam	735	10YR 6/4	10YR 5/8			granular	weak	friable

Comments

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

DAVID LAUCE (Designer/Inspector) (Signature) 1174 (License #) 10/16/24 (Date)

OSTP Soil Observation Log

Project ID:



Client/ Address: 67119 348th Pl Legal Description/ GPS: 12-0-023504

Soil parent material(s): (Check all that apply) Summit Shoulder Back/Side Slope Foot Slope Tree Slope Slope shape

Landscape Position: (check one) Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Vegetation: Wooded Soil survey map units: 204B Slope%: 3 Elevation:

Weather Conditions/Time of Day: 10:11 AM Clear Date: 10-16-20

Observation #/Location: Parent & Observation Type: PSR

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure		
							Shape	Grade	Consistence
5	Loam	735	10YR 3/2				granular	Dark	friable
16	Silt Loam	735	10YR 6/4				granular	Dark	friable
17	Silt Loam	735	10YR 6/4				granular	Dark	friable

Comments

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

Designer/Inspector: David Auld Signature: [Signature] License #: 1154 Date: 10-16-20